



REPLY TO  
ATTENTION OF:

DEPARTMENT OF THE ARMY

SAVANNAH DISTRICT, CORPS OF ENGINEERS  
P.O. BOX 889  
SAVANNAH, GEORGIA 31402-0889

June 30, 1997

Operations Division

Leo Francendese  
U.S. Environmental Protection Agency, Region IV  
Atlanta Federal Center  
100 Alabama Street  
Atlanta, Georgia 30303

Dear Mr. Francendese:

This letter is a follow-up to a meeting we had on June 12, 1997, at the Hercules Plant in Brunswick, Georgia.

We have completed inspections of the weirs and dike. Inspections were performed on June 18, 1997, and June 23, 1997. Inspection revealed that there were no substantially low areas in the dike. The weirs were also inspected.

We are proposing to repair the weirs on Terry Creek Dredge Disposal Area in accordance with the enclosed specifications and drawings.

We would appreciate your written concurrence with our proposal as soon as possible, to enable us to promptly proceed with this action. If you have any further questions regarding this action, please contact Kathie Morgan at 912-652-5018.

T. Alan Garrett  
Navigation Project Manager

Enclosures

Copies Furnished:

Wayne Quinn  
Hercules Incorporated  
P.O. Box 1517  
Brunswick, GA 31521-1517

**Proposed Weir Repair and Sediment Retention Measures  
for Terry Creek Disposal Area**

- 1) Remove all existing weir boards. Replace with 4" X 4" X 4' pressure treated boards. 1/4" steel spacers will be placed between each layer of boards as shown in Enclosure 3. Excavate as necessary for proper installation.
- 2) Determine limits of weir footings.
- 3) Install 5' steel posts as shown on Enclosures 4 & 5. Embed approximately 2 feet.
- 4) Attach wire reinforced sediment retention fence to posts and per fence manufacturer's specifications. (Enclosure 6)
- 5) Inspect after next significant storm event and periodically thereafter.